




1. GRATING IS GALV STEEL, 1/8" X 1" BEARING BAR, 1 3/16" CENTER TO CENTER
2. TOUCH UP CUT EDGES AND DAMAGED GALVANIZED SURFACES WITH ZINC-RICH REPAIR COATING.

PART NO	DESCRIPTION	A	B
S107-1	LARGE GRATING	36	48
S107-2	SMALL GRATING	21.65	48



BOMFab

FICTIONAL FABRICATION SOLUTIONS

BOMFab LLC
 1234 Fake Way
 BOM Island, New BOM 12345
 info@bomfab.com
 www.bomfab.com

DRAWN:	B. TABULATOR	DATE:	05/23/2025
CHECKED:	A. MATERIAL	DATE:	05/23/2025
APPROVED:	NO. ENGINEER	DATE:	05/23/2025

[illegible]

DWG. NO.: S107

DRAWING TITLE:

GRATING

REVISION:
A

UNLESS OTHERWISE SPECIFIED:

PRINTS ARE FOR BOM TABULATOR
DEMONSTRATION ONLY AND BELONG TO BOM
TABULATOR LLC. NO ENGINEERING
CALCULATIONS, DESIGN VALIDATION, OR
FITNESS-FOR-SERVICE REVIEW HAS BEEN
PERFORMED. NOT FOR PRODUCTION OR
CONSTRUCTION. BUILDING IS AT YOUR OWN
RISK, NOT BOM TABULATOR LLC.

SCALE:	SHEET SIZE:	SHEET:
1:10	ANSI B	1 OF 1